
NEWVIEW AERIAL

SAMPLE DRONE ROOF INSPECTION REPORT

Maintenance roof report

Prepared for Facilities team

Illustrative example using a fictional property. The diagram shows how a finding can be located and referenced in a client report.



R03 | East drainage outlet

Flat roof with internal outlets

Diagram for illustration

Visual observation

Leaves are visible around the outlet grille. A dark area nearby is recorded for comparison at the next visit.

Suggested follow-up

Ask the maintenance contractor to inspect and clear the outlet, then photograph it again from the same viewpoint.

Scope and limits

Discharge capacity and the condition of concealed drainage runs cannot be determined from aerial imagery.

Example roof photography

These images show the type of aerial coverage available. The photos are reference examples from a separate flight. The fictional finding on page 1 does not refer to the property pictured here.



01 | Roof overview



02 | Roof detail