
NEWVIEW AERIAL

SAMPLE DRONE ROOF INSPECTION REPORT

Home owners roof report

Prepared for Homeowner

Illustrative example using a fictional property. The diagram shows how a finding can be located and referenced in a client report.



R06 | Front eaves gutter

Pitched tiled house roof

Diagram for illustration

Visual observation

Leaf material is visible in a short length of gutter below the front roof slope. The overview shows its position by the front corner.

Suggested follow-up

Share the annotated location with a roofer or gutter contractor and ask whether clearing or closer inspection is needed.

Scope and limits

The report shows what can be seen from outside. It does not confirm drainage performance or hidden damage.

Example roof photography

These images show the type of aerial coverage available. The photos are reference examples from a separate flight. The fictional finding on page 1 does not refer to the property pictured here.



01 | Roof overview



02 | Roof detail